

## Waste Site Reclassification Form

Date Submitted: 6/3/2004	Operable Unit(s):	200-UR-1	Control	Number: 2004-085
Originator: C. R. Webb	Waste Site ID:	UPR-200-W-85		
Bhamas 272 6572	Type of Reclassific	ation Action:		
Phone: 373-5573	Rejected:	0		
	No Action:		•	
	Interim Close Closed Out:	d Out:	*	: .
This form documents agreemen	t among the partie	s listed below author	izing classific	ation of the subject
unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.				
		tes will occur at a fut	ure date.	
Description of current waste site condition:				
In April 1982, a multi-purpose transfer box was moved from the 221-T railroad cut to the cement pad behind the 2706-T Building. While parked on the pad, liquid was observed dripping from the box. The apparent cause of the leak was a weld failure on the outside sheathing				
covering the concrete shell. Contamination levels up to 100,000 counts per minute were found on the ground. The contamination was cleaned up at the 2706-T pad area. The railroad track from the 2706-T Building to the 221-T railroad cut was surveyed and no contamination				
was detected.				
A new building (2706-TA) has been built on	top of the cement pad.			
			**	
_				
Basis for reclassification:				
The cement pad was decontaminated in 1982. A new building (2706-TA) was constructed on top of the cement pad. The release is not physically marked or posted. It is recommended this site be reclassified to No Action.				
			· .	· · · · · · · · · · · · · · · · · · ·
	•			
	•			
				-
S. Beneross	St	R	7	4/19/04
DOE Project Manager	( v Signatur	re.		, , o Date
John B. Price		R.B.K	•	7/14/04
Ecology Project Manager	Signatur	re ·		Date
		· ·	•	Date
EPA Project Manager	Signatur	e ·		Date